







C. Using a Phillips screwdriver (or drill), screw the 4 screws (F) through the main support (A) holes into the back side of the table base (G). Once screwed in all the way, flip table over and it is ready for use!



